
AOS Thu 03 Apr 2014 12:59:42 AOS
CoordSystem:121F04 SensorID:121f04 Axis:sum Windowing:Hanning
Cuttoff(Hz):200 df(Hz):0.2441 Sample/Sec:500 PSD size:2048 Overlap(%):0 TimeRes.(sec):4.096
Is this ECLSS equipment doing something atypical between about GMT 11:25 and 12:40 or so, operating at about 167 Hz, which is 10,000 RPM?
Frequency (Hz)
Time
Amplitude(Log10(g^2/Hz))
-5.00
-9.00
-13.00